



afc

Docket No.: TESSERA 3.0-132 DIV
(PATENT)

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Letters Patent of:
Joseph Link

Patent No.: 6,709,469

Issued: March 23, 2004

For: SPACER PLATE SOLDER BALL PLACEMENT
FIXTURE AND METHODS THEREFOR

Certificate
JUN 04 2004
of Correction

Certificate of Correction Branch
Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450

REQUEST FOR CERTIFICATE OF CORRECTION PURSUANT TO 37 CFR 1.322

Dear Sir:


Enclosed herewith is an original and one copy of a Certificate of Correction with respect to the above-identified U.S. Patent.

The corrections indicated should be made as the application originally filed does not contain such errors. There is no requirement for payment of a fee since the errors were made by the Patent Office.

We look forward to early return of the copy of the Certificate of Correction duly certified.

Dated: May 27, 2004

Respectfully submitted,

By 

Michael J. Doherty
Registration No.: 40,592
LERNER, DAVID, LITTENBERG, KRUMHOLZ &
MENTLIK, LLP
600 South Avenue West
Westfield, New Jersey 07090
(908) 654-5000
Attorney for Applicant

494944_1.DOC

JUN 17 2004

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO. : 6,709,469
DATED : March 23, 2004
INVENTOR(S) : Joseph Link

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 1, line 32, after "there through" insert -- . --.
Column 1, line 60, after "point" insert -- . --.
Column 2, line 22, after "therein" insert -- . --.
Column 2, line 25, after "therein" insert -- . --.
Column 2, line 54, after "thereof" insert -- . --.
Column 3, line 13, after "terminals" insert -- . --.
Column 3, line 31, after "element" insert -- . --.
Column 4, line 26, after "condition" insert -- . --.
Column 5, line 23, after "surfaces" insert -- . --.
Column 5, line 38, " t rough" should read --there through--.
Column 5, line 56, "tern" should read --terminals--.
Column 6, line 6, "close up" should read --close-up--.
Column 6, line 8, "carder" should read --carrier--.
Column 6, line 18, "SA" should read --5A--.
Column 6, line 38, "tee" should read --the--.
Column 6, line 46, "close up" should read --close-up--.
Column 7, line 2, "surge" should read --surface--.
Column 7, line 24, after "component" insert -- . --.
Column 7, line 27, after "Corporation" insert -- . --.
Column 7, line 35, after "region" insert -- . --.
Column 8, line 21, after "herein" insert -- . --.

MAILING ADDRESS OF SENDER:
Michael J. Doherty
LERNER, DAVID, LITTENBERG, KRUMHOLZ & MENTLIK, LLP
600 South Avenue West
Westfield, New Jersey 07090

PATENT NO.: 6,709,469

No. of additional copies: 1

Column 8, line 31, after "process" insert -- . --.
Column 9, line 8, "therethroug" should read --there through--.
Column 9, line 9, "tend" should read --then--.
Column 10, line 14, after "sheet" insert -- . --.
Column 10, line 34, "em" should read --enlarged--.
Column 10, line 37, "pings" should read --openings--.
Column 12, line 38, after "therewith" insert -- . --.
Column 12, line 58, after "re-solidify" insert -- . --.
Column 13, line 41, "s" should read --surface--.
Column 14, line 49, "bas" should read --has--.
Column 14, line 61, "raining" should read --retaining--.

MAILING ADDRESS OF SENDER:

Michael J. Doherty

LERNER, DAVID, LITTENBERG, KRUMHOLZ & MENTLIK, LLP

600 South Avenue West

Westfield, New Jersey 07090

PATENT NO.: 6,709,469

No. of additional copies: 1

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO. : 6,709,469
DATED : March 23, 2004
INVENTOR(S) : Joseph Link

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 1, line 32, after "there through" insert -- . --.
Column 1, line 60, after "point" insert -- . --.
Column 2, line 22, after "therein" insert -- . --.
Column 2, line 25, after "therein" insert -- . --.
Column 2, line 54, after "thereof" insert -- . --.
Column 3, line 13, after "terminals" insert -- . --.
Column 3, line 31, after "element" insert -- . --.
Column 4, line 26, after "condition" insert -- . --.
Column 5, line 23, after "surfaces" insert -- . --.
Column 5, line 38, " t rough" should read --there through--.
Column 5, line 56, "tern" should read --terminals--.
Column 6, line 6, "close up" should read --close-up--.
Column 6, line 8, "carder" should read --carrier--.
Column 6, line 18, "SA" should read --5A--.
Column 6, line 38, "tee" should read --the--.
Column 6, line 46, "close up" should read --close-up--.
Column 7, line 2, "surge" should read --surface--.
Column 7, line 24, after "component" insert -- . --.
Column 7, line 27, after "Corporation" insert -- . --.
Column 7, line 35, after "region" insert -- . --.
Column 8, line 21, after "herein" insert -- . --.

MAILING ADDRESS OF SENDER:

Michael J. Doherty
LERNER, DAVID, LITTENBERG, KRUMHOLZ & MENTLIK, LLP
600 South Avenue West
Westfield, New Jersey 07090

PATENT NO.: 6,709,469

No. of additional copies: 1

Column 8, line 31, after "process" insert -- . --.
Column 9, line 8, "therethroug" should read --there through--.
Column 9, line 9, "tend" should read --then--.
Column 10, line 14, after "sheet" insert -- . --.
Column 10, line 34, "em" should read --enlarged--.
Column 10, line 37, "pings" should read --openings--.
Column 12, line 38, after "therewith" insert -- . --.
Column 12, line 58, after "re-solidify" insert -- . --.
Column 13, line 41, "s" should read --surface--.
Column 14, line 49, "bas" should read --has--.
Column 14, line 61, "raining" should read --retaining--.

MAILING ADDRESS OF SENDER:

Michael J. Doherty

LERNER, DAVID, LITTENBERG, KRUMHOLZ & MENTLIK, LLP

600 South Avenue West

Westfield, New Jersey 07090

PATENT NO.: 6,709,469

No. of additional copies: 1